## Inspection Report - Dry Film Thickness

BAMR Example\Pipeline #234\ Coating Thickness






| Project            |                 |
|--------------------|-----------------|
| Name               | BAMR Example    |
|                    |                 |
| Labels             |                 |
| Calibration Foil   | 100.5 microns   |
| 0                  |                 |
| Gauge              |                 |
| Туре               | Elcometer 456/3 |
| PCB Serial #       |                 |
| Serial #           |                 |
| User ID            |                 |
|                    |                 |
| Probe              |                 |
| Type               |                 |
| Serial #           | EG12345-891     |
| Calibration        |                 |
|                    | C               |
| Calibration Method | Smooth          |
| Batch              |                 |
| Datti              |                 |

| Dutti         |                       |    |
|---------------|-----------------------|----|
| Name in Gauge |                       |    |
| User ID       | Coating Thickness     |    |
| Created Date  | 03-Jul-07 10:05:00 AM |    |
| Updated Date  | 03-Jul-07 10:05:00 AM |    |
|               |                       |    |
| Statistics    |                       |    |
| # Pandings    |                       | 30 |

| # Readings               | 30        |
|--------------------------|-----------|
| Mean                     | 40.13 μm  |
| Maximum                  | 84.0 µm   |
| Minimum                  | 5.0 μm    |
| Standard Deviation (σ)   | 17.92 μm  |
| Mean + 3σ                | 93.89 µm  |
| Mean - 3σ                | -13.62 μm |
| Coefficient of Variation | 44.7%     |

| Limits     |         |                  |           |
|------------|---------|------------------|-----------|
| High Limit | 59.0 µm | # Readings Above | 5 (16.7%) |
| Low Limit  | 9.0 µm  | # Readings Below | 1 (3.3%)  |



## Notes


Data transfered from Elcometer 456

## Inspection Report - Dry Film Thickness

BAMR Example\Pipeline #234\ Coating Thickness



Image.jpg



## Inspection Report - Dry Film Thickness

BAMR Example\Pipeline #234\
Coating Thickness



|  | Thickness (µm)  |
|--|---|
| 1  | 50.0  |
| 2  | 50.0  |
| 3  | 40.0  |
| 4  | 30.0  |
| 5  | 20.0  |
| 6  | 50.0  |
| 7  | 60.0  |
| 8  | 40.0  |
| 9  | 50.0  |
| 10   |   |
| 11   | 60.0  |
| 12   | 40.0  |
| 13   |   |
| 14   |   |
| 15   |   |
| 16   |   |
|  | <del>424.0</del>  |
|  |   |
|  | Incorrectly measured  |
| 17   | •   |
| 17<br>18   | 70.0  |
|  | 70.0<br>50.0  |
| 18   | 70.0<br>50.0<br>40.0  |
| 18<br>19   | 70.0<br>50.0<br>40.0  |
| 18<br>19<br>20                                     | 70.0<br>50.0<br>40.0<br>30.0  |
| 18<br>19<br>20<br>21                               | 70.0<br>50.0<br>40.0<br>30.0<br>20.0  |
| 18<br>19<br>20<br>21<br>22                         | 70.0<br>50.0<br>40.0<br>30.0<br>20.0<br>40.0<br>50.0                                |
| 18<br>19<br>20<br>21<br>22<br>23                   | 70.0<br>50.0<br>40.0<br>30.0<br>20.0<br>40.0<br>50.0                                |
| 18<br>19<br>20<br>21<br>22<br>23<br>24             | 70.0<br>50.0<br>40.0<br>30.0<br>20.0<br>40.0<br>50.0<br>35.0                        |
| 18<br>19<br>20<br>21<br>22<br>23<br>24<br>25       | 70.0<br>50.0<br>40.0<br>30.0<br>20.0<br>40.0<br>50.0<br>35.0<br>11.0                |
| 18<br>19<br>20<br>21<br>22<br>23<br>24<br>25       | 70.0<br>50.0<br>40.0<br>30.0<br>20.0<br>40.0<br>50.0<br>35.0<br>11.0<br>5.0<br>66.0 |
| 18<br>19<br>20<br>21<br>22<br>23<br>24<br>25<br>26 | 70.0<br>50.0<br>40.0<br>30.0<br>20.0<br>40.0<br>50.0<br>35.0<br>11.0<br>5.0<br>66.0 |