Coating Thickness Accessories

USB Bluetooth® Transmitter / Receiver

Required for use with the Elcometer 456 Mk 3, if PC does not have built-in *Bluetooth*® Transmitter / Receiver

Description	Part Number
USB *Bluetooth*® Transmitter / Receiver	T99920130

RS232 - USB Cable Accessory

You can now connect your multiplexer to the PC via the hot pluggable USB port and keep your serial port free for other equipment such as digital cameras, modems, barcode scanners, PDA Organiser (also Palm V), etc.

Hot pluggable Software on CD For Windows 98/2000/ME, including user manual, are also supplied allowing instant use.

Description	Part Number
RS232 - USB Cable Accessory	T99916716

Jumbo Hand Grip

Ideal for precision placement for the most accurate results on flat and curved surfaces. Simply place the probe inside the Jumbo Hand Grip and take measurements.
The Jumbo Hand Grip can be used with the following probes:
  o F1 Standard; F2 Standard; F4 Standard; F5 Rebar; N1 Standard; N4 Standard; FNF Standard

Description	Part Number
Jumbo Hand Grip - F & NF Probes	T9997766-
Jumbo Hand Grip - FNF Probe	T99913225

V-Probe Adaptor

Ideal for precision placement for the most accurate results on large diameter curved surfaces such as pipes and cylinders. Simply place the probe inside the V-Probe and start taking measurements.

The V-Probe Adapter can be used with the following probes:
  o F1 Standard; F2 Standard; F4 Standard; F5 Rebar; N1 Standard; N4 Standard; FNF Standard

Description	Part Number
V-Probe Adaptor - F & NF Probes	T9997381-
V-Probe Adaptor - FNF Probe	T99913133

Soft Material / Blanket Probe

Ideal for taking precision readings on soft coatings or print blankets. The wide, flat base design acts as a load spreader, reducing the total force at a single point.

Description	Part Number
Soft Material / Blanket Probe	T35511963

Probe Placement Jig

For the most reliable and repeatable coating thickness measurements, making the gauge the score highly in repeatability and reproducibility studies. Ideal for small and large components alike.

The Probe Placement Jig can be used with the following probes:
- o F1 Standard; F2 Standard; F4 Standard; F5 Rebar; N1 Standard; N4 Standard; FNF Standard, Miniature Probes

Description	Part Number
Probe Placement Jig	T95012880
Component Hand Vice – a simple vice to hold small components	T95013028
Cable Release Assembly – ideal for remote measurements	T95012888
N4 Probe Adaptor – must be purchased for use with N4 Probes	T95015589
FNF Probe Adaptor – must be purchased for use with FNF Probes	T95015961
Miniature Probe Adaptor - must be purchased for use with Miniature Probes	T95016896
RS232 - USB Cable Accessory	T99916716

Infrared Printer

This printer has been specifically selected for gauges which have IR output. The battery operated unit is an ideal choice for printing out individual readings and statistical information - without using a cable.

The Elcometer Infrared Printer can be used with the following gauges with IR output:

Description	Part Number
Soft Material / Blanket Probe	T35511963

Elcometer Dot Matrix Mini Printer

This serial & parallel portable printer has an internal rechargeable battery and can accept a signal from all Elcometer Gauges with a cable output. Using a cable allows the user to be confident that all data stored in the gauge will be printed, without loss or interruption.

This Dot Matrix Printer can be used with the following instruments with cable data output:
Elcometer 206
Elcometer 355
Elcometer 456

Description	Part Number
Elcometer Dot Matrix Printer	X###9964C

replace ### with the model number to receive the correct data cable