

elcometer® 139 ABC Amine Blush Check



When using amine cured epoxy resins coatings in a multi layer system, if the original coating cures in a low ambient temperature or in a high humidity environment, a surface oiliness or exudates may occur.

"Amine Blush" or "Sweating" as it is commonly referred to, leads to inter-coating adhesion failure.

Features

- Easy to use
 - Spray the ABC Solution onto a test filter pad and apply to the surface.
 - Check for colour change if amine is present.
 - After test, flush with clean, fresh water.
- Immediate result if amine blush is present.
- Each kit is suitable for 75+ tests.

Shipping List

Each unit is supplied in a carrying case for easy transportation to the site and comes complete with:

- ABC Solution
- Protective Gloves
- Test Filter Pads
- Sealable Sample Bags

Part Number

Model	Description	Part Number
Elcometer 139	Elcometer 139 ABC Amine Blush Check	E139----1

